




After EGRP® System Installed



Before Installation



Site Analysis

Cincinnati Reds Brandon Phillips Field Baseball Field Cincinnati, OH - USA

Solution

April 2014, an EGRP® System was engineered and installed along the warning track in right and center fields.

Project Description



In the winter of 2014 Parjana met with The Cincinnati Reds Community Fund Executive Director to discuss field drainage issues on one of their premier Community Fund Fields (Brandon Phillips Field).

There was a chronic water drainage issue. Right and Center fields did not drain as quickly as the rest of the field, hence the field was unusable. Practices and games had to be cancelled and often this section of the field had to be roped off and designated as out of play.

Results - Play Ball



This portion of the field has drained and has allowed play on the field, even after heavy rains. The Cincinnati Reds are very pleased with the results, and field has been ready for play all year. Erosion of the warning track is significantly reduced.

