



Warwick School Rugby Field Project Warwick, UK

“Since installation the area of the pitch feels firmer under foot than it was and the grass growth has become stronger. [...] The system has acclimated and is successfully draining the pitch, in an area which was previously one of the most water logged areas on the whole grounds”

-G. Delday
Head Groundsman



Project Description

After any substantial rainfall, the school's rugby field flooded and was deemed unusable. As a result, ground maintenance was compelled to pump the water or cancel the game.

In August 2013, Parjana® was contacted about the problem and installed the EGRP® system on the field.

Results

Since December 2013, Warwick School suffered record rainfalls, but were able to conduct games without interruption all season long due to the installation of the EGRP® system. In January 2014, it rained nearly 2 inches in 48 hours yet the field remained playable.